
The Magic Stapler

New generation

The essential tool for plastic repair.



- ▶ Rotative head
- 2 lenght of electrode
- Lighting LED
- ▶ 6 level of power
- 2 welding tip



Fix quickly broken plastic





Fog lamps

Dont throw






Dashboard



Door trim










> Adjustable in current power:

The power of the current depends on which of the 6 different levels chosen using button UP and DOWN and allows a perfect control during the stapling or the welding steps.

The power can be swiched from 2 to 40 Amp.

Adjustable in rotation:

You can 90° rotate the head for an optimal position in work



○ Adjustable in position

Holes to place the staples are provided in 3 different angles in order to always be in the better working conditions.



> Multifunction: Stapler and welder

You can plug and unplug the welding tips in one step.

Set up the power level 5 or level 6 to turn red the welding tip in less than 8 seconds.




> Filling powder:

Heat the powder with the Magic Stapler welding tip and melt together the plastic fibber and powder in order to fill the repair. Powder is very flexible.

>Adjustable in lenght:

Electrode can be easily swiched from 2 to 15 centimeter in order to work in difficult place to access.

Repair strongly: using specific step process



MixPlast® research and development works to make it stronger and easier.

The two following samples of plastic have all been repaired using the Magic Stapler, but using slightly different methods. The same force was then exerted on all 2 samples to test the strength and the rigidity of each repair and therefore determine the most effective method of repair. Sample number one proved to be the only repair that was able to withstand the force that was exerted. To create the solid repair as shown in sample one, 2 x 3649 staples are embedded into the plastic edge and secured into place using a small piece of 3650 stainless steel wire mesh. 3645 and 3649 are then embedded in alternation along the break as needed.




Shape to fit: easy to curve




3649 staple is easy to shape in order to fit plastic tabs and brackets or broken surface curves.

> Shape to fit: easy to curve

3658 staple allows to adjust the angle without changing the pin connection



Use the special drill Ref:571 on the outside of the part in order to create a channel along the break.



3690 Plastic Powder is a very flexible hot melt filler, designed to fill in small and medium spaces after the repair with staple or wire mesh product. Must be used with Magic Stapler welder.



Mix Sarl ZA de l'Avenir - 30600 VESTRIC & CANDIAC - France Tel:+33 466 711 447 - E-mail: mixplast@mix.fr - Web: www.mix.fr

Kit includes

1 x Carton Case100 x3641 U shape staple1 x Magic Stapler gun100 x3642 V shape staple2 x Long electrode L 150mm100 x3643 N shape staple2 x Short electrode L 20mm50 x3645 Break repair st

2 x Short electrode L 20mm
1 x 3644-U Shape welding tip
2 x 3645 Break repair staple
3 x 3645 Break repair staple
3 x 3645 Break repair staple

1 x 3644-O shape welding tip 50 x 3668 Adjustable outside angle staple

1 x 3690 plastic powder 50 x 3649 shape to fit staple

1 x 3644-II Cleaning brush 1 x 3650 Wire mesh

1 x 36891 repair & finishing cream 1

Instruction manual - warranty

Charger



The essential tool for plastic repair.